

[T-33]

A study of MOS characteristics of reoxidized HfO₂ thin film for gate oxide applications

Dongwon Lee*, Hyo-Jick Choi*, Seok-Woo Nam**+, Suheun Nam*, Dae Hong Ko*,

*Department of Ceramic Engineering, Yonsei University 134

Shincheon-Dong, Seodaemoon-Ku, Seoul 120-749, Korea

+R&D Center Semiconductor Samsung Electronics Co.

We investigated the change of the microstructure which depend on the thickness of Hf films deposited by DC magnetron sputtering on Si substrate for gate dielectric application. Also, we estimated the electrical property and the microstructure of the interlayer between the thin HfO₂ films and Pt and Al gate electrode. The Hf films reoxidized by the RTP(rapid thermal processing) were analyzed by spectroscopic ellipsometry, AFM, XRD, XPS, and HR-TEM. We observed small grains of the HfO₂ film due to the local crystallization of the as-deposited Hf film $\sim 90\text{\AA}$ by HR-TEM. The thickness of the interfacial layer between hafnium oxide and Si substrate was about 8\AA . After RTP treatment at 800°C in N₂ ambient, the thickness of interfacial layer was equal to that of as-deposited film. For 500\AA thick as-deposited Hf film, the HfO₂ layer at the surface was observed about 55\AA by HR-TEM. The HfO₂ layer increased to be 90\AA at 800°C in N₂ ambient. Especially, the HfO₂ grains were shown not only at the surface of the Hf film but also at the silicide(Hf₅Si₄) grain boundaries. And the buckling of the silicide film on the Si substrate was locally observed due to the stress generated during the silicide and hafnium dioxide formation. XRD peaks indicated the formation of silicide after RTP treatment over 700°C . We evaluated C-V and I-V of the MOSCAP structures in the Pt/Hf($\sim 100\text{\AA}$)/Si and Al/Hf($\sim 100\text{\AA}$)/Si, and it demonstrated that the capacitance and the leakage current level of the MOS structures were changed upon the temperature of RTP treatments.