Images in Cardiovascular Disease

Check for updates

More Is Not Always More: A Timely Reminder Why Not to Use Too Much Hardware

Dibbendhu Khanra (), MD, DM¹, Gaurav Panchal (), MRCP², Rory Dowd (), MRCP¹, Nakul Chandan (), MRCP¹, and Sanjiv Petkar (), MD, FRCP¹

¹Heart and Lung Centre, Department of Electrophysiology and Devices, New Cross Hospital, Royal Wolverhampton NHS Trust, Wolverhampton, United Kingdom ²Department of Cardiology, The Royal Stoke University Hospital, Stoke-on-Trent, United Kingdom

A healthy 79-year-old male with non-ischaemic cardiomyopathy underwent an implantable cardioverter defibrillator (ICD) insertion 7 years ago following presentation with a haemodynamically significant ventricular tachycardia. A 9 French dual coil ventricular and a 6 French atrial lead were inserted transvenously. While considering an upgrade to a biventricular device due to symptomatic heart failure, striking bilateral symmetrical varicosities over the chest and abdomen (**Figure 1A and B**), suggestive of superior vena cava (SVC) obstruction, were noted. Echocardiography showed severely impaired left ventricular systolic function. On questioning, he admitted to having a fuzzy head and dizziness when bending over. Chest X-ray showed normally positioned dual coil ICD from a left




Figure 1. Striking bilateral symmetrical varicosities over the chest and abdomen (A, B), suggestive of SVC obstruction. Chest X-ray showed normally positioned dual coil ICD (C). Computed tomography venogram confirmed stenosis of the SVC (D).

ICD: implantable cardioverter defibrillator, SVC: superior vena cava.

 Received:
 May 21, 2021

 Revised:
 Jun 16, 2021

 Accepted:
 Jun 27, 2021

 Published online:
 Jul 19, 2021

Address for Correspondence: Dibbendhu Khanra, MD, DM

Heart and Lung Centre, Department of Electrophysiology and Devices, New Cross Hospital, Royal Wolverhampton NHS Trust, Wolverhampton, WV10 0QP, United Kingdom. Email: dibbendhu.khanra@nhs.net

Copyright © 2022 Korean Society of Echocardiography

This is an Open Access article distributed under the terms of the Creative Commons Attribution Non-Commercial License (https:// creativecommons.org/licenses/by-nc/4.0/) which permits unrestricted non-commercial use, distribution, and reproduction in any medium, provided the original work is properly cited.

ORCID iDs

Dibbendhu Khanra Dibbendhu Khanra Dibbendhu Khanra Dibhendhu Khanra Dibheta Katalara Kataaa Kataa Kataa Katalara Katalara Katalar

Conflict of Interest

The authors have no financial conflicts of interest.

Author Contributions

Data curation: Khanra D, Panchal G, Chandan N; Supervision: Petkar S; Validation: Petkar S; Visualization: Petkar S; Writing - original draft: Khanra D; Writing - review & editing: Dowd R, Petkar S. infraclavicular approach (**Figure 1C**). Computed tomography venogram confirmed stenosis of the SVC (**Figure 1D**). SVC obstruction is a known entity (in up to 30% cases) in the context of bulky ICD leads. However, it remains asymptomatic and thus often goes unnoticed until the need for device upgrade with a new lead or extraction arises.¹⁾ Having said that, venous engorgement such as in our case is very rare. One of the common causes of stenosis at the right atrium (RA) - SVC junction is the SVC coil of a dual coil ICD. Superiority of dual, versus single coil leads, in terms of defibrillation efficacy remains to be proven.²⁾ Moreover, the SVC coil increases lead complexity, cost, risk of lead failure, and lead removal.³⁾ Also, in the absence of a bradycardia indication, the potential of an additional atrial lead to enhance arrhythmia discrimination, reduce inappropriate shocks, rate of hospitalization and mortality has not been borne out by scientific studies.⁴⁾ A SVC coil induces not only wall adhesions, but also sclerotic reorganisation of the venous wall resulting in stenosis and obstruction.¹⁾

In our patient, we are managing his heart failure with optimal medical therapy including angiotensin receptor antagonist and neprilysin inhibitor and sodium glucose transporter 2 inhibitor. We anticipate the need for a venoplasty of the SVC-RA junction if we do ever consider upgrading his ICD with a new left ventricular lead. In retrospect, the SVC obstruction may have been prevented if a single coil ICD was implanted in the first place. In contemporary practice of ICD implantation, an SVC coil can cause more trouble than be of benefit to a patient.

REFERENCES

- Lickfett L, Bitzen A, Arepally A, et al. Incidence of venous obstruction following insertion of an implantable cardioverter defibrillator. A study of systematic contrast venography on patients presenting for their first elective ICD generator replacement. *Europace* 2004;6:25-31.
 PUBMED | CROSSREF
- Sunderland N, Kaura A, Murgatroyd F, Dhillon P, Scott PA. Outcomes with single-coil versus dual-coil implantable cardioverter defibrillators: a meta-analysis. *Europace* 2018;20:e21-9.
 PUBMED | CROSSREF
- Epstein LM, Love CJ, Wilkoff BL, et al. Superior vena cava defibrillator coils make transvenous lead extraction more challenging and riskier. J Am Coll Cardiol 2013;61:987-9.
 PUBMED | CROSSREF
- Zeitler EP, Sanders GD, Singh K, et al. Single vs. dual chamber implantable cardioverter-defibrillators or programming of implantable cardioverter-defibrillators in patients without a bradycardia pacing indication: systematic review and meta-analysis. *Europace* 2018;20:1621-9.
 PUBMED | CROSSREF